

Rock Failure Assessment on Paleo-Collapse in Case of the Prasat Hin Pan Yod tourist site, Satun Geopark, Thailand

Sakda Khundee, Sarinthip Kukham, Saowaphap Uthairat, Visuttipong Kererattanasathian, Kittikorn Tima and Tanawat Rakhangkul

Environmental Geology Division, Department of Mineral Resources (DMR), Bangkok, Thailand

**Corresponding author: geol.envi@gmail.com*

Received 26 December 2022; Accepted 9 June 2023.

Abstract

Rockfall and rockslide incidents are currently severe geohazards affecting marine tourism in Thailand. Lately, some tourist sites, located both in the Gulf of Thailand and the Andaman Sea, were prohibited to access. Prasat Hin Pan Yod, the study area developed from a paleo-collapse sinkhole on Khao Yai Island of Satun province, is now confronting unsafe caused by rockfall and rockslide hazards as well. The study applied the integration of simple multi-criteria in GIS, traditional stereographic projection analysis, and Slope Mass Rating (SMR) to determine the rock mass instability of limestones and to find a safe route entrancing the Prasat Hin Pan Yod tourist site. Various discontinuities on the outcrop slopes relating to geomorphological features such as sea cliff, sea cave, and a former broken block of the rockslide were investigated and assessed the rock mass stability.

The study result shows that the dominant wedge failure of rockfall can occur in many spots of the Prasat Hin Pan Yod tourist site. Small pieces of broken limestone hanging on high spots and also filling in rock niches are often found during the field investigation. Rock fragments splitting off the rock face may fall away whenever it is triggered by heavy rain or ground shaking. Direct toppling failure is the comparative subordinate of the rockfall hazard. Its negative impact is similar to wedge failure and difficult to perform risk management as well. Planar failure and toppling failure seem to be low scores and rarely occur the two big severe events happened from that failure modes and revealed obvious field evidence of broken blocks. The precedent event was caused by toppling failure and the latest, February 20, 2021, was originated by planar failure. The previous route getting through the Prasat Hin Pan Yod chamber is not suitable now. Depending on the high SMR score and a few joint intersections causing the geohazard, a narrow strait located between the former broken block and sea cliff is determined as the new safe route for tourists. Moreover, Kayaks should be adopted to use for moving through the narrow strait and permitted for in and out. The tourist numbers visiting the site should be controlled. A Helmet is suggested for more safety as it can protect the tourists from the hanging rock falling from high places.

Keywords: RMR, SMR, Prasat Hin Pan Yod, Satun, Rock failure, Rockslide, Rockfall

1. Introduction

Rockfall and rockslide incidents have more frequently occurred in marine attractions in Thailand. Especially, during the southwest monsoon that affected the peninsular region. It causes the base rocks in southern Thailand which are dominant carbonate-rich rocks (ex. limestone, dolomite, and gypsum) that are easy to weather and erosion, so the karst topography is generally formed in this area. Most karst features are formed along with weaknesses in the rock mass, such as faults, joints, fractures, and bedding

planes, that karst features decrease rock stability and lead to cause geohazard. Prasat Hin Pan Yod is one of the famous coastal karst landforms in Thailand. The rockfall incident happened here on February 20, 2021, occurred in the north part of the Prasat Hin Pan Yod chamber, Khao Yai Island (Fig. 1). Fortunately, this incident did not cause people to die or be injured. However, spectacular karst morphology has been turned to be a dangerous area.

Tourists and locals were not allowed to visit that place. People in Satun provincial area were indigent due to the loss of tourism revenue. The aims of this study are to assess the anticipated

failure of rockfall and rockslide and to find new comparatively safe routes through the Prasat Hin Pan Yod tourist site.



Fig. 1: The latest rockslide big event happened in the north part of the Prasat Hin Pan Yod chamber, Khao Yai Island on February 20, 2021

2. Study area

The Prasat Hin Pan Yod tourist site is located in the north part of Khao Yai Island which is a limestone island in the Andaman Sea, La-Ngu district, Satun province, south of Thailand. Prasat Hin Pan Yod is one of geosites within Satun Geopark which is the first UNESCO Global Geopark in Thailand. The Satun Geopark was endorsed by the UNESCO Executive Board on April 17, 2018. The Geopark covers four districts: Thung Wa, La-Ngu, Manang, and a part of Mueang Satun, and also consists of two national parks and one wildlife sanctuary. The Global Geopark is established by the concept of sites and landscapes of international geological significance, which are managed with a holistic concept of protection, education, and sustainable development.

3. Geology and geohazard

Based on the lithological descriptions on the geological map scale 1:50,000 published by Sinsakul (1988) and Tiyaipairach (2004), Khao Yai Island is abundantly covered by carbonate rocks, which can be classified into stratigraphically lower and upper parts. The lower part is medium to thick bedded dolomitic limestone with partly brown mudstone and the upper part is thicker to massive bedded. Locally, the northern part of Khao Yai Island, where the Prasat Hin Pan Yod chamber is located, mainly consists of dark grey argillaceous limestone and

stromatolitic limestone with dominant fossils. Some fossils are occasionally found on the planar failure that is sub-parallel limestone to the bedding plane. Wongvanish (1990) and Meesook (2014) correlated the rocks in this area to the Lae Tong Formation of the Thung Song Group. Their depositional environment is interpreted as pelagic deeper water during the Ordovician period. Thepju et al. (2017) classified onshore karst features in the Satun Geopark into 13 types which are (1) wall karst, (2) stromatolitic karst, (3) pinnacle, (4) cone and tower, (5) knob, (6) Karren or lapies, (7) stone forest, (8) polje, (9) sinkhole or doline, (10) karst spring or karst seepage, (11) karst waterfall, (12) karst lake, and (13) cave. These features are mostly exokarst-subaerial occurring in the Lae Tong Formation and the Rung Nok Formation of the Ordovician Thung Song Group. The Lae Tong Formation is characterized by thin-bedded argillaceous limestone and interbedded with pinkish-brown shale at the lower sequence. The Rung Nok Formation, overlying the Lae Tong Formation with a gradual boundary, consists of dark grey to grey limestone, medium to thick-bedded limestone with stromatolitic interbedded with occasional stylolite and massive dolomite.

The Prasat Hin Pan Yod chamber is naturally a paleo-collapse sinkhole. Based on the sinkhole classification presented by Waltham et al. (2005), a collapse sinkhole is a roof collapse happening on unstable limestone beneath, particularly cavernous and high fracturing rock. The sinkhole originated on the hinge zone of a small asymmetry anticline whose fold axis is orientated nearly north-south (NNE-SSW) and gently plunged at 11° in a direction 014 (NNE). Limestone bedding planes have an average dip angle of 25° in direction 320 (NW) and dip at 15° in direction 035 (NE). A well-defined bimodal clustering on stereonet shows the dominant strike directions of joint and fracture in limestone rock mass have approximately four directions. The discontinuous plans are trending nearly north (NNW-SSE to NNE-SSW), northwest-southeast (NW-SE), northeast-southwest (NE-SW), and east-west (E-W). Thinner bedded limestones generally show narrower spacing of joints and higher fracture density compares to massive limestones. Due to the southwest monsoon climate and sea process, the erosional karstic surface is well developed on strongly fractured limestone, particularly in the upper part of its succession. According to karstic landforms, the imagination of people when they look at limestone pinnacles exposed on islands it resembles castle-like features with a thousand peaks.

There is a small chamber of the formal sinkhole surrounded by spectacular limestone pinnacles and hides in the sea cliff. Its geometry is a small oval-shaped room with a longest of 20 meters and the shortest distance of 10 meters. The Prasat Hin Pan Yod tourist site locates in the rocky intertidal zone of the island. By the action of currents and waves, sediments and other detrital material have entered the chamber via sea caves and deposited in a low-energy sinkhole hiding a sea cliff. The small beach will be exposed to air for only a short period when low tide. Tourists can enter in sightseeing site from March to mid-May. Coastal massive limestone is no exception of strongly eroded by the action of the sea. Various karst types are generally found in the intertidal zone: notch, cave, cavity, stack, and column. Enlargement of cave size and

connected passage networks has been still processed by both dissolution and erosion until the present time and invaded toward limestone chamber or collapse sinkhole. Cave passages lack the strength to span limestone overburden and create unsafety ground conditions for use.

Far from the Prasat Hin Pan Yod to the south direction of 150 meters, another rectangular-shaped formal collapse sinkhole with a long diameter of 150 meters across can be visible on remote sensing images. It has occurred on major joint/fault intersections having strike orientations on the north-south and northeast-southwest. The comparative size is larger than the others on the Google images (Fig. 2). Because that area is shallowed by sediment deposit and covered by dense water grasses, which karstic characteristics can classify as the older age than a sinkhole of the Prasat Hin Pan Yod. According to the karst engineering classification introduced by Waltham and Fookes (2003), the Prasat Hin Pan Yod can categorize as Complex to Extreme Karst. Besides specific lithology and geological structures, rock strength has been degraded by that various karst features leading to severe geohazard occurrence of the rock mass.

Based on the DMR field evidence, the rockslide occurrence may briefly conclude in four parts. First: erosion of fractured and cavernous limestone by sea, due to the location placing at the narrow strait of Khao Yai Island and the other island on the northern side, strong waves and rapid currents can enter cave passages to hit unstable rock columns that partly support cave roof, because of hydraulic power of the waves and compression of air within a confined space provide the fissures in rock mass widen and deepen and lead to having a broken column. Second: as a result of the supporting column is being broken, the loss of rock strengths cannot carry limestone overburden at the upper part. Third: the massive limestone volumes suddenly separated from the weakened sea cliff along major linear faults. Fourth: the upper part slides through rock mass sub-parallel bedding plane / along low angle fault and falls in the north direction into the sea, hiding the traditional entrance of the chamber. The fragment block of the rock-




Fig.2: the Prasat Hin Pan Yod chamber showing oval shaped collapse sinkhole that occurred next to an older rectangular shape (Blue arrow)

-slide location is not far from the precedent rock topple. As mentioned above, the paleo-collapse sinkhole at the Prasat Hin Pan Yod can be a recurrence, particularly on the edge of the chamber.

Based on the orthophotos visual interpretation, geohazards in the Prasat Hin Pan Yod area have ever occurred at least 2 times: prior to the event on February 20, 2021, there was a precedent topple block sitting nearby the latest rockslide. A huge block of limestone was broken along a major joint/fault and fallen to sea by a toppling failure mechanism. Rockfall and rockslide in the Prasat Hin Pan Yod will happen in the near future.

Sinkhole hazards naturally overspread in the Satun provincial area due to underlying limestone bedrock. The sinkhole potential map of Satun province was hurriedly produced after the big earthquake accompanied by the severe tsunami event in 2004 and the map was firstly published by DMR (2005). The mapping of sinkhole types relating to soil materials, especially dropout sinkholes, was the main task. The potential sinkhole area was delineated by the simple approach of limestone bedrock or mountain proximity. As a consequence, the limestone mountain is generally surrounded by areas of a high potential sinkhole. There have no collapse sinkholes both onshore and offshore represented on the map. To study rock failure, the sinkhole potential area classification must be studied in more detail.

According to Sinsakul et al. (2002), the Satun coastline erosion mapping was initially conducted by the DMR prior to 2002, and the mission of coastal management has been responsible by the Department of Marine and Coastal Resources (DMCR). To monitor shoreline erosion, Khundee et al. (2019) used the Real-Time Kinematic Global Navigation Satellite Systems (RTK-GNSS) method for the beach erosion investigation from the Pak Nam Bara to Ao Noon in the Mu Ko Petra National Park. Beach erosion is the topic study that is more focusing on Thailand. Hard structures are used to reduce the wave action of the sea. Erosion at rocky coasts has rarely been explored by organizations, so data is not adequate to support the study of limestone coast collapse.

Based on the intensity of the Mercalli scale, the seismic hazard map of Thailand published by DMR (2016) is categorized into 5 levels which are I-III, IV, V, VI, and VII. In Satun province, active faults have never been discovered, and the intensity of Satun is I-III which is classified as the lowest level. However, coastal karst terrain can be affected by the Klong Marui fault which is an active strike-slip fault system in southern Thailand. It extends in a northeast-southwest direction from Phuket towards Surat Thani province, and the distance from Satun provincial area to the Klong Marui fault zone is about 290 kilometers.

At coastal karst, tourists often take time in an attractive place without realizing that there is danger from geohazards. Rock failure mode: a planar, wedge, or topple can cause rockslide or rockfall in high fractured limestone of marine karst terrain as the latest rockslide event happened on February 20, 2021. For the safety of tourists, rock mass stability and slope mass stability have to be investigated in the Satun Geopark and Thailand National Park. Moreover, recommendations or guidelines for rock reinforcement are introduced to reduce the opportunity of geohazard risk.

4. Methodology

Six processes were conducted for rock failure assessment (Fig. 3). They are described below.

(1) Making of an orthophoto map obtained from drone flying, lineaments and boundary of limestone rock types can be extracted from the orthophoto by the method of visual interpretation.

(2) Mapping the sinkhole potential area of Satun province.

(3) Mapping preliminary rockfall zonation by the multi-criteria analysis in GIS which the map using for field checking and determining rock stability study in detail.

(4) Collecting the data relating to rock mass discontinuity and clues of former rockfall, and to estimate Rock Mass Rating (RMR) values in field investigation.

(5) Slope Mass Rating (SMR) assessment, the first step is to assess the mode of failure that may be originated rockfall type and to evaluate the stability of outcrop slope due to discontinuity cutting on.

(6) Writing a report, presenting to the provincial office and local government, and giving recommendations for reducing rockfall impacts on tourist sites.

The equipment using in field investigation were geological hammer, compass (Breithaupt), tape measure or ruler, and Schmidt hammer. The Software used for data analysis and displays the imagery maps were Agisoft Metashape, DIPS, and ArcMap.

Field survey was took place at the end of the year 2021 from the coastal limestone outcrop that is considered as having a high potential area of geohazards at paleo-collapse sinkhole and may cause medium to high negative impact. The direct measurement or investigation in the field was composed of four data sets of primary data: photos obtained from drone flying, Rock Mass Rating (RMRb) parameters, slope face orientation of outcrops, and various discontinuity in karstic limestone.



5. Result and discussion

5.1 Orthophoto map obtained from drone flying

The DJI Mavic 2 Pro, a lightweight Unmanned Aerial Vehicles (UAV), was used for achieving the Khao Yai Island image. The traverse line was covered the north part of Khao Yai Island where the Prasat Hin Pan Yod located. According to the time that taking photo was nearly at noon, it allowed dark shadow appeared along the edges of sea cliff, sea cave, and eastern side of the paleo-collapse sinkhole. The images obtained from UAV were totally 1,202 images covering 0.065 square kilometers. For orthophoto making, Agisoft Metashape software was adopted to conduct data processing. The output orthophoto had a Ground Sampling Distance (GSD) of 4.15 centimeters. For data quality control, the horizontal position value (East and North coordination) is quite precise, but its elevation data still have some error. The orthophoto is used for exploring the orientation of rock mass discontinuity and to concentrate on unstable zone due to marine erosion.

5.2 Mapping sinkhole potential area of Satun province

The first sinkhole potential map was published in 2005 by DMR, then it has been updated in 2022 by using GIS. The simple overlay technique of relating factors was utilized for analysis. The five factors adopted for the improvement of sinkhole zoning have consisted of the density of lineament intersection, lineament density, distance to lineament, stream density, and distance to stream. Enhanced sinkhole potential area is classified into five levels which are very low,



low, medium, high, and very high. The grid cell resolution of the map is 30x30 meters. The high potential area is abundantly covered in the Koh Kao Yai Islands, particularly in the Prasat Hin Pan Yod chamber (Fig. 4). Types of the sinkholes as classified by Waltham et al. (2005) do not conduct by the DMR due to the scarcity of fundamental analysis data. However, an enhanced sinkhole potential map is still useful for limestone failure assessment in the Prasat Hin Pan Yod area.

5.3 Rockfall hazard zonation

To examine the overview rock mass stability and select suitable locations for collecting field data, rockfall hazard zonation of the Prasat Hin Pan Yod chamber had mapped by using the approach of simple multi-criteria in GIS. The five basic factors were integrated to analyze and delineate rockfall hazard areas (Fig. 5). They are consisting of density of lines (Fig. 5A), density of intersection points (Fig. 5B), lineament proximity (Fig. 5C), slope (Fig. 5D), and aspect (Fig. 5E). The rockfall hazard zonation resulted in a grid cell size of 5x5 meters and was categorized into 5 classes including very low, low, moderate, high, and very high. The map shows moderate to high level hazard seems to be happening along sea cliffs and at the entrance of tourist sites as well (Fig. 6)

5.4. Rock Mass Rating (RMR) evaluation

The RMR is a geomechanics classification system for rock mass. A sum of each rating values provide overall comprehensive index of rock mass quality or RMR value (Bieniawski, 1989). The RMR values can be estimated through 9 locations (Fig. 7) distributed along the rim of the chamber, a big broken block of limestone, and the new expected entrance of the tourist site. The RMR values ranged from 53 to 62 (Table 1). The result shows that the RMR of the bedded limestone has lower values than the massive limestone. Thinner bedding is stratigraphically overlying on the Massive limestone, so it is hard to explore the unstable rock when the rock mass locates in the high places of the Prasat Hin Pan Yod area.

5.5 Rock failure analysis using Stereographic projection

The rock failure analysis using stereographic projection found that the wedge failure of rockfall has more potential and happens more frequently than toppling and planar, respectively (Table 2). After field checking, the wedge failure was found that tends to occur a small event of rockfall with a small block pending in the cavity and mainly caused unsafely in the tourist site. For toppling failure, oblique toppling and direct toppling have the same situation as planar failure but will be happened in particular locality. Planar failure is the lowest potential of rockfall, but big events with huge block can be happened in recent time, for example, the rockfall event at the Prasat Hin Pan Yod tourist site on February 20, 2021.

The making of stereographic projection from the discontinuous planes on the outcrop slope was used for modeling rock mass failures or rockfall types that can occur in a planar, wedge, or toppling. The rock mass failures were next used to calculate the SMR adjustment factors. Some stations are selected to show as samples of the stereographic projection analysis which shown below (Figs 8, 9, 10 and 11).

5.6 Slope Mass Rating (SMR) assessments

The SMR was developed by Romana (1985) for evaluating rock slope stability. The SMR assessment in the Prasat Hin Pan Yod area can be divided into 4 sub-areas with totally 26 of SMR stations (Fig. 12).

- 1) The area of rockslide on February 20, 2021 that nowadays hiding the Prasat Hin Pan Yod entrance, in which was represented by the stations of 1A to 1E, 3A to 3D, and 7A to 7F.
- 2) The strait locating between linearly sea cliff and the former huge topple of rock mass, in which was illustrated by the stations of 4A, and 6A to 6C.
- 3) A high eroded sea cave with clues of former rockfall and thin column supporting with high potential hazard, which representative stations was composed of 2A to 2C.




Fig.5 Five factors for preliminary rockfall hazard mapping using GIS; (A) density of lines, (B) density of intersection points, (C) Lineament proximity, (D) slope, and (E) aspect.




Fig. 6 preliminary rockfall hazard map, the Prasat Hin Pan Yod tourist site, Satun province.

Table 1 The summary of RMR value obtained from the field investigation

Station	UCS	RQD	joint spacing	Persistent	Aperture	joint roughness	Filling	Weathering	GW	Discontinuity orientation	RMR
1	54.29	75.38	117.78 cm	4.87 m	20-30 mm	rough	none	moderate	Flowing	none	55
	7	17	15	2	0	5	6	3	0	0	
2	54.83	95.68	60,80, 100cm	6.05 m	5-10 mm	rough	none	moderate	Flowing	Dip 0-20 irrespective of strike	53
	7	20	15	2	0	5	6	3	0	-5	
3	61.78	75.38	118.78cm	10.69 m	20-30 mm	rough	none	moderate	Flowing	none	54
	7	17	15	1	0	5	6	3	0	0	
4	63.39	95.7	65 cm	3 m	20 mm	very rough	none	moderate	Flowing	none	59
	7	20	15	2	0	6	6	3	0	0	
5	56.84	92.09	60 cm	3,10 m	5 mm	rough	none	moderate	tidal	none	59
	7	20	15	2	1	5	6	3	0	0	
6	61.78	93	110 cm	3 m	12 mm	very rough	none	moderate	Flowing	none	59
	7	20	15	2	0	6	6	3	0	0	
7	61.24	75.38	70 cm	10 m	10 mm	rough	none	moderate	Flowing	none	55
	7	17	15	2	0	5	6	3	0	0	
8	54.83	91.48	60, 100 cm	3 m	5 mm	very rough	none	moderate	tidal	none	62
	7	20	15	4	1	6	6	3	0	0	
9	58.23	96.91	64 cm	12.6m	10 mm	rough	none	moderate	tidal	none	57
	7	20	15	1	0	5	6	3	0	0	

Note: UCS = Uniaxial Compressive Strength, RQD = Rock Quality Designation which was proposed by Deere (1964), and GW = Groundwater



Fig. 7 showing stations of measured Rock Mass Rating overlying on orthophoto

Table 2 The summary of rock failure analysis using stereographic projection

Station	No.	Face slope (Dip direction/ Dip angle)	Failure mode					
			Planar (%)	Wedge (%)	Toppling (%)			
					Direct	Oblique	Flexural	Base plane
1	1A	003/85	0	25.15	15.2	9.36	0	0
	1B	355/88	0	42.69	16.96	9.36	0	21.05
	1C	087/88	26.32	59.06	10.53	12.87	0	36.84
	1D	317/89	10.53	50.88	2.92	25.15	0	10.53
	1E	233/78	21.05	35.09	21.64	34.5	10.53	21.05
2	2A	325/80	0	1.11	11.11	47.78	21.43	0
	2B	255/83	14.29	40	5.56	13.33	0	14.29
	2C	225/84	21.43	64.44	10	4.44	0	21.43
	2D	353/85	0	3.33	18.89	50	21.43	7.14
3	3A	020/89	20	46.67	0	0	0	40
	3B	095/89	33.33	32.38	10.48	1.9	6.67	40
	3C	328/87	6.67	35.24	0.95	9.52	0	26.67
	3D	122/87	0	18.1	13.33	3.81	6.67	6.67
4	4A	260/78	12.5	45	12.5	17.5	18.75	18.75
5	5A	062/85	0	0	0	10	0	20
6	6A	004/81	0	1.9	3.33	39.52	4.76	14.29
	6B	163/72	0	0.95	8.1	33.81	28.57	0
	6C	337/81	0	5.24	0	26.67	0	14.29
7	7A	245/78	9.09	22.92	35.04	12.12	12.12	9.09
	7B	264/83	6.06	18.75	17.23	9.28	3.03	6.06
	7C	324/77	9.09	21.97	0.57	4.55	24.24	18.18
	7D	222/77	9.09	17.61	29.92	13.26	18.18	9.09
	7E	290/82	9.09	23.67	4.92	4.92	12.12	12.12
	7F	110/82	12.12	42.8	6.63	10.23	12.12	21.21
8	8A	034/85	0	17.65	5.88	13.07	0	22.22
9	9A	022/85	10	22.22	4.44	22.22	0	30




Fig. 8: showing stereographic projection of the station 2C




Fig.9: showing stereographic projection of the station 3B




Fig. 10: showing stereographic projection of the station 4A




Fig. 11: showing stereographic projection of the station 7D



Fig. 12: showing stations of Slope Mass Rating (SMR) assessment

4) A small beach within the Prasat Hin Pan Yod chamber that exposed whenever low tide, the representative stations were 8A and 9A.

SMR was calculated and classified according to Romana (1985). The SMR assessment in detail of station 2A and station 4A was partly shown in Table 3 and Table 4, respectively. The overall result of the 26 stations was depicted in Table 5 and was shortly summarized in Table 6

Station 1A to 1E is the previous entrance of the Prasat Hin Pan Yod tourist site which is concealed from a huge block of the rockslide. Stations 1A to 1E had an SMR value of 27.5-70.1275, which was classified as bad to good (Table 5). The dominant SMR values were categorized as a good class. There were two intersections of joint sets of wedge failure, and one of the joint planes of toppling failure was classified as a normal class. Additionally, two points intersections of joint sets had an SMR score of 27.5, which was classified as low class. For such the representative SMR, wedge failure of rockfall type has so higher potential to have occurred in stations 1A to 1E. The three intersections (Table 6), plunging to nearly north (NNE) nearly east, and also southwest

(SW) may be originated from wedge failure of rockfall type. As mentioned, the tourist route for the inner chamber should not pass stations 1A, 1C, and 1E.

Station 2A (Fig. 13) is a place of the sea cave that locating beneath a massive limestone roof and supported by a thin column. The evidence of a former rockfall had two big blocks. Due to the high energy of currents and waves, rock collapse might have occurred in nearly future. The SMR value's wedge failure (Table 3 and 5) was categorized as bad and very bad. The SMR value was 8-18 and 25.5-33, respectively. Wedge failure of rockfall type has a higher potential to have occurred than planar and toppling failure. Moreover, bedding rockfall blocks is one of the high potential hazards, and it is difficult to determine by the SMR approach.

Station 3A-3D is the lower part of the broken rock that remained from the rockslide event in February 2021. The SMR value was range 18-69 (Table 5), and it was almost categorized as a good class and normal class. The SMR value of direct toppling failure was partly categorized as very bad (two values) to bad (one value), meanwhile, four SMR value

Table 4 Some of the evaluating result of Slope Mass Rating (SMR) at the station 2A

Failure mode	Face slope	joint sets	Trend	Plunge	RMR	F1	F2	F3	F4	F1F2F3+F4	SMR	Class	Stability
Planar	225/84	120/80	-	-	53	105 0.15	80 1	-4 -50	Natural 15	7.5	60.5	Normal	Partially stable
	225/84	318/89	-	-	53	91 0.15	89 1	5 -6	Natural 15	14.1	67.1	Good	Stable
	225/84	140/86	-	-	53	85 0.15	86 1	2 -6	Natural 15	14.1	67.1	Good	Stable
	225/84	68/19	-	-	53	157 0.15	19 0.15	-65 -60	Natural 15	13.65	66.65	Good	Stable
Wedge	225/84	251/88, 316/89	232	80	53	7 0.85	80 1	-4 -50	Natural 15	-27.5	25.5	Bad	Unstable
	225/84	251/81, 140/86	210	78	53	15 0.7	78 1	-6 -50	Natural 15	-20	33	Bad	Unstable
	225/84	251/81, 212/80	223	80	53	2 1	80 1	-4 -50	Natural 15	-35	18	Very Bad	Completely unstable
	225/84	251/81, 120/80	184	68	53	41 0.15	68 1	-16 -60	Natural 15	6	59	Normal	Partially stable
	225/84	251/81, 181/80	212	78	53	13 0.7	78 1	-6 -50	Natural 15	-20	33	Bad	Unstable
	225/84	316/89, 140/86	227	39	53	2 1	39 1	-45 -60	Natural 15	-45	8	Very Bad	Completely unstable
	225/84	316/89, 212/80	231	79	53	6 0.85	79 1	-5 -50	Natural 15	-27.5	25.5	Bad	Unstable
	225/84	181/80, 140/86	210	79	53	15 0.7	79 1	-5 -50	Natural 15	-20	33	Bad	Unstable
	225/84	181/80, 316/89	230	75	53	5 0.85	75 1	-9 -50	Natural 15	-27.5	25.5	Bad	Unstable
	225/84	181/80	-	-	53	224 0.15	1 1	164 -25	Natural 15	11.25	64.25	Good	Stable
Direct Toppling	225/84	120/80	-	-	53	285 0.15	1 1	164 -25	Natural 15	11.25	64.25	Good	Stable
	225/84	316/89	-	-	53	89 0.15	1 1	173 -25	Natural 15	11.25	64.25	Good	Stable
	225/84	140/86	-	-	53	265 0.15	1 1	170 -25	Natural 15	11.25	64.25	Good	Stable
	225/84	120/80	-	-	53	285 0.15	1 1	164 -25	Natural 15	11.25	64.25	Good	Stable
Flexural Toppling	225/84	316/89	-	-	53	89 0.15	1 1	173 -25	Natural 15	11.25	64.25	Good	Stable
	225	140/89	-	-	53	265 0.15	1 1	173 -25	Natural 15	11.25	64.25	Good	Stable
	225	140/89	-	-	53	265 0.15	1 1	173 -25	Natural 15	11.25	64.25	Good	Stable

of wedge failure was classified as a bad class. The very bad to bad SMR class of direct toppling failure had a joint plan dipping to the east. The bad SMR class of wedge failure had five intersects of joint sets plunging to the northwest and nearly north (Table 6) and it maybe caused by wedge failure of rockfall type. Although the SMR value of planar failure is classified as a normal class, the rockslide can be occurred as well particularly, in the case of repeatedly column supporting broken. For safety, the tourist route should not pass station 3A-3D getting through the Prasat Hin Pan Yod chamber.

Station 4A (Fig. 13) had SMR value of 23-74, which is classified as bad to good. The five intersects of joint sets were classified as bad class (Table 4 and Table 5). The intersection of

joint sets plunges to the west and southwest which shows potential wedge failure of rockfall hazard type (Table 6). Tourists may be slightly affected by small pieces of rock wedge that pending at high places. Fortunately, distance passing station 4A and getting through is quite short (not over 3 meters).

Station 5A had SMR value of 70.25-74 (Table 5 and 6) and all SMR values were classified as good class. It can be said that limestone rock mass having stable and safety for tourist.

Station 6A to 6C had SMR score of 56.65-73.1 (Table 5 and Table 6) which all SMR values were classified as normal to good class. There was none of bad to very bad. However, rockfall hazard may be originated by both direct and oblique toppling

Table 4 Some of the evaluating result of Slope Mass Rating (SMR) at the station 4A

Failure mode	Face slope	joint sets	Trend	Plunge	RMR	F1	F2	F3	F4	F1F2F3+F4	SMR	Class	Stability
Planar	260/78	360/90	-	-	59	100	90	12	Natural	15	74	Good	Stable
						0.15	1	0	15				
	260/78	083/82	-	-	59	177	82	4	Natural	14.1	73.1	Good	Stable
						0.15	1	-6	15				
	260/78	327/83	-	-	59	67	83	5	Natural	14.1	73.1	Good	Stable
						0.15	1	-6	15				
Wedge	260/78	310/79, 327/83	262	74	59	2	74	-4	Natural	-35	24	Bad	Unstable
						1	1	-50	15				
	260/78	360/90, 251/61	270	60	59	10	60	-18	Natural	-36	23	Bad	Unstable
						0.85	1	-60	15				
	260/78	251/61, 327/83	250	61	59	10	61	-17	Natural	-36	23	Bad	Unstable
						0.85	1	-60	15				
	260/78	242/79, 310/79	276	77	59	16	77	-1	Natural	-20	39	Bad	Unstable
						0.7	1	-50	15				
	260/78	251/61, 310/79	240	61	59	20	61	-17	Natural	-27	32	Bad	Unstable
						0.7	1	-60	15				
	260/78	242/79, 327/83	271	78	59	11	78	0	Natural	-2.5	56.5	Normal	Partially stable
						0.7	1	-25	15				
	260/78	242/79, 251/61	327	23	59	67	23	-55	Natural	11.4	70.4	Good	Stable
						0.15	0.4	-60	15				
Direct Toppling	260/78	360/90	-	-	59	80	1	168	Natural	11.25	70.25	Good	Stable
						0.15	1	-25	15				
	260/78	083/82	-	-	59	357	1	160	Natural	11.25	70.25	Good	Stable
						0.15	1	-25	15				
	260/78	327/83	-	-	59	357	1	161	Natural	11.25	70.25	Good	Stable
						0.15	1	-25	15				
	260/78	310/79	-	-	59	130	1	157	Natural	11.25	70.25	Good	Stable
						0.15	1	-25	15				
Flexural Toppling	260/78	360/90	-	-	59	80	1	168	Natural	11.25	70.25	Good	Stable
						0.15	1	-25	15				
	260/78	327/83	-	-	59	113	1	161	Natural	11.25	70.25	Good	Stable
						0.15	1	-25	15				
	260/78	251/61	-	-	59	189	1	139	Natural	11.25	70.25	Good	Stable
						0.15	1	-25	15				
	260/78	310/79	-	-	59	130	1	157	Natural	11.25	70.25	Good	Stable
						0.15	1	-25	15				

Station 7A to 7F is the huge block of planar rockslide that occurred by column supporting broken in the event of February 2021. The investigated stations had SMR values of 19-70 (Table 5 and Table 6), which were classified as very bad to good. The dominant SMR values were categorized as a good class. Two intersections of joint sets of wedge failure had SMR value of 19, which were categorized as a very bad class. There were five intersections of joint sets of wedge failure, which were classified as a bad class (28-34.3).

Furthermore, four intersections of joint sets of wedge failure and one joint plan of direct toppling were classified as a normal class, which still had partially stable. The rock movement direction was mainly plunging west to northwest (W-NW) and southeast to southwest (SE-SW) (Table 6). As mentioned,

tourists should not close up the huge block of planar rockslide located nearby sea cliff because of rockfall, particularly small wedge shape hanging on the high place.

Station 8A had SMR score of 35-7.77 (Table 5) which the dominant values were classified as good class (Table 6). There was only one intersects of joint sets that classified as bad class. Rockfall hazard may be caused by wedge failure. Because of intersection of joint sets plunging to northeast (NE), tourist should be aware pieces of rock wedge that pending at high place in the Prasat Hin Pan Yod chamber.

Station 9A had SMR score of 29.5-69.6 (Table 5). The SMR value was mostly classified as good class. There was only one joint plan dipping to nearly north (NNE) (Table 6), planar failure may be originated rockfall in the Prasat Hin Pan Yod chamber.



Fig. 13: photograph of station 2A (right) and station 4A (left)

5.7 Support guidelines for stabilization

Most SMR values are classified the rock slope as a good class. Some SMR values have lower than 10 due to error of under estimation or rock failure occurred already. None of slope having an SMR value below 10 exist in nature. SMR value below 20 may cause the rock slope failure very quickly. Detailed studies should be carried out where an SMR value is less than 40 (or IVa to Va) because tourist sites are in danger and the rock slope should be stabilized by the integration of various measures: bolting/anchors, shotcrete, diversion drains and removal of rock fragment at high place as following in Table 7. In National Park and Satun Geopark, a safe slope angle should be determined to increase SMR to 60.

6. Conclusions

Preliminary rockfall zonation mapping is useful for field investigation. For the better quality of mapping, field data and more parameters relate to rockfall occurrence have to be added to GIS analysis. Paleo-collapse sinkhole at coastal zone can be recurrent at the place having weakened or cavernous rockmass and high force of the sea process. The new collapse often happens at the rime of sinkhole chamber by various failure mechanisms: planar, wedge, and topple, and the event show as rockslide and rockfall.

The rockfall is defined as the one of the major geohazards in the Prasat Hin Pan Yod area. It is mainly caused by the wedge failure mechanism. Topple and planar failure is subordinate to rockfall and rockslide hazards.

The former route getting through the chamber (stations of 1A to 1E, 3A to 3D, and 7A to 7F) should be avoided due to having high potential rockfall of wedge failure. Toppling and planar failure have a lower potential to be originated rockfall hazards. The rockfall hazard is expected to have occurred in small events, but it is high frequency.

The line of stations 4A and 6A to 6C are said to be the safest new route to getting through the chamber. However, the wedge failure of rockfall can occur within a short distance of a sea cliff (about 3 meters). A helmet, one of the simple tools, can protect tourists from fallen rock which it is pending on sea cliffs or high places. For the linear strait, the route is narrow, and slightly strong waves in some time, kayak carrying tourists passing should be controlled and permit a one for in and out.

A limitation of the tourist number is essential for the Prasat Hin Pan Yod chamber. Tourists can spend their time in the chamber, but they must be aware of the rockfalls of wedge failures, and avoid visitation near sea caves that it locates beneath massive limestone.

Because the Prasat Hin Pan Yod has located nearby a strait, the strong wave and currents in the monsoon period can cause the broken block to be moved, titling, or more fracturing. Rock mass stability and slope mass stability still need long-term site investigation and monitoring at the sea cliffs and the rim of the sinkhole chamber; therefore, Real-time kinematic (RTK) surveying will use for detecting rock displacement

Table 5 The result of SMR assessment in the Prasat Hin Pan Yod tourist site

Station	No.	RMR	Face slope	Failure analysis of Stereonet analysis			SMR		A number of SMR class in failure mode								
				Failure modes	%	Number of joint or intersection	Range		Mode	SMR value	SMR class	Very Bad	Bad	Normal	Good	Very good	
							min	max									
1	1A	003/85	Planar	0	0												
			Wedge	25.15	5	27.5	69.1	none	Good	0	1	0	4	0			
			Direct Toppling	15.2	8	52.5	66.25	66.25	Good	0	0	1	7	0			
			Oblique Toppling	9.36	0												
	1B	355/88	Planar	0	0												
			Wedge	42.69	7	52.5	68.65	62.5	Good	0	0	1	6	0			
			Direct Toppling	16.96	5	66.25	66.25	66.25	Good	0	0	0	5	0			
			Oblique Toppling	9.36	0												
	1C	087/88	Planar	26.32	2	61	66.25	none	Good	0	0	0	2	0			
			Wedge	59.06	3	27.5	66.25	none	Good	0	1	0	2	0			
			Direct Toppling	10.53	4	66.25	66.25	66.25	Good	0	0	0	4	0			
			Oblique Toppling	12.87	0												
	1D	317/89	Planar	10.53	2	61	62.5	none	Good	0	0	0	2	0			
			Wedge	50.88	5	50	62.5	61	Good	0	0	1	4	0			
			Direct Toppling	2.92	5	66.25	66.25	66.25	Good	0	0	0	5	0			
			Oblique Toppling	25.15	0												
	1E	55	233/78	Planar	21.05	1	70.1275	70.1275	70.1275	Good	0	0	0	1	0		
			Wedge	35.09	3	27.5	61	61	Good	0	1	0	2	0			
			Direct Toppling	21.64	8	66.25	66.25	66.25	Good	0	0	0	8	0			
			Oblique Toppling	34.5	1	66.25	66.25	66.25	Good	0	0	0	1	0			
2-30	2A	53	325/80	Planar	0	0											
			Wedge	1.11	2	59	64.25	59, 64.25	Normal, Good	0	0	1	1	0			
			Direct Toppling	11.11	13	64.25	64.25	64.25	Good	0	0	0	13	0			
			Oblique Toppling	21.43	1	64.25	65.25	66.25	Good	0	0	0	1	0			
	2B	255/83	Planar	14.29	3	60.5	67.1	none	Good	0	0	1	1	0	2		
			Wedge	40	9	48	60.5	60.5	Normal	0	0	9	0	0			
			Direct Toppling	5.56	6	64.25	64.25	64.25	Good	0	0	0	6	0			
			Oblique Toppling	13.33	0												
	2C	225/84	Planar	21.43	4	60.5	67.1	67.1	Good	0	0	1	3	0			
			Wedge	64.44	9	8	59	25.5	Bad	2	6	1	0	0			
			Direct Toppling	10	4	64.25	64.25	64.25	Good	0	0	0	4	0			
			Oblique Toppling	4.44	0												
	2D	353/85	Planar	0	2	60.5	60.5	60.5	Normal	0	0	2	0	0			
			Wedge	3.33	4	59	66.65	59, 66.65	Normal, Good	0	0	2	2	0			
			Direct Toppling	18.89	6	64.25	64.25	64.25	Good	0	0	0	6	0			
			Oblique Toppling	50	2	64.25	65.25	66.25	Good	0	0	0	2	0			
3	3A	54	020/89	Planar	20	3	60	61.5	60	Good	0	0	2	1	0		
			Wedge	46.67	15	34	67.65	52.5	Normal	0	3	7	5	0			
			Direct Toppling	0	4	65.25	65.25	65.25	Good	0	0	0	4	0			
			Oblique Toppling	0	0												
	3B	095/89	Planar	33.33	4	60	65.4	60	Normal	0	0	2	2	0			
			Wedge	32.38	14	45	67.65	65.4, 67.65	Good	0	0	3	11	0			
			Direct Toppling	10.48	9	9	60	60	Normal	2	1	6	0	0			
			Oblique Toppling	6.67	6	60	60	60	Normal	0	0	6	0	0			
	3C	328/87	Planar	6.67	1	61.35	61.35	61.35	Good	0	0	0	1	0			
			Wedge	35.24	9	27	65.4	65.4	Good	0	1	2	6	0			
			Direct Toppling	0.95	5	65.25	66.25	67.25	Good	0	0	0	5	0			
			Oblique Toppling	9.52	0												
	3D	122/87	Planar	0	0	0											
			Wedge	18.1	4	59.4	67.65	none	Normal, Good	0	0	2	2	0			
			Direct Toppling	13.33	11	47.75	69	65.25	Good	0	0	4	7	0			
			Oblique Toppling	3.81	4	65.25	68.1	65.25	Good	0	0	0	4	0			
4A	59	260/78	Planar	12.5	3	73.1	74	73.1	Good	0	0	0	0	3	0		
		Wedge	45	7	23	70.4	23	Bad	0	5	1	1	0				
		Direct Toppling	12.5	4	70.25	71.25	72.25	Good	0	0	0	4	0				
		Oblique Toppling	17.5	4	70.25	70.25	70.25	Good	0	0	0	4	0				
5A	59	062/85	Planar	0	0												
		Wedge	0	0													
		Direct Toppling	0	0													
		Oblique Toppling	10	3	70.25	74	70.25	Good	0	0	0	3	0				
6	6A	59	004/81	Planar	0	0											
			Wedge	1.9	11	66.5	73.1	73.1	Good	0	0	0	11	0			
			Direct Toppling	3.33	15	52.75	70.25	70.25	Good	0	0	2	0	0			
			Oblique Toppling	39.52	3	70.25	74	70.25	Good	0	0	0	3	0			
	6B	163/72	Planar	0	0												
			Wedge	0.95	4	73.1	74	74	Good	0	0	0	4	0			
			Direct Toppling	8.1	16	52.75	70.25	70.25	Good	0	0	4	12	0			
			Oblique Toppling	33.81	2	70.25	70.25	70.25	Good	0	0	0	2	0			
	6C	337/81	Planar	0	0												
			Wedge	5.24	5	65	73.1	66.5	Good	0	0	0	5	0			
			Direct Toppling	0	0												
			Oblique Toppling	26.67	15	70.25	70.25	70.25	Good	0	0	0	15	0			
	7-10	7A	55	245/78	Planar	9.09	6	61	66.4	61	Good	0	0	0	6	0	
				Wedge	22.92	11	46	68.5	68.5	Good	0	0	1	10	0		
				Direct Toppling	35.04	7	66.25	70	66.25	Good	0	0	0	7	0		
				Oblique Toppling	12.12	4	66.25	66.25	66.25	Good	0	0	0	4	0		
7B		264/78	Planar	6.06	6	61	66.4	61	Good	0	0	0	6	0			
			Wedge	18.75	8	28	66.4	61, 62.35, 66	Good	0	1	0	7	0			
			Direct Toppling	17.23	8	66.25	70	66.25	Good	0	0	0	8	0			
			Oblique Toppling	9.28	3	66.25	66.25	66.25	Good	0	0	0	3	0			
7C		324/77	Planar	9.09	3	61	62.5	61	Good	0	0	0	3	0			
			Wedge	21.97	12	28	68.65	62.5	Good	0	1	2	9	0			
			Direct Toppling	0.57	6	66.25	67.25	68.25	Good	0	0	0	6	0			
			Oblique Toppling	4.55	10	66.25	70	66.25	Good	0	0	0	10	0			
7D		227/77	Planar	9.09	7	61	69.1	62.5	Good	0	0	0	7	0			
			Wedge	17.61	5	19	62.35	none	Good	1	1	1	2	0			
			Direct Toppling	29.92	8	61	61	61	Good	0	0	0	8	0			
			Oblique Toppling	13.26	5	61	61	61	Good	0	0	0	5	0			
7E		290/82	Planar	9.09	5	61	66.4	61	Good	0	0	0	5	0			
			Wedge	23.67	12	28	62.35	61	Good	0	2	0	10	0			
			Direct Toppling	4.92	9	66.25	70	66.25	Good	0	0	0	9	0			
	Oblique Toppling		4.92	6	66.25	66.25	66.25	Good	0	0	0	6	0				
7F	110/82	Planar	12.12	4	61	61	61	Good	0	0	0	4	0				
		Wedge	42.8	12	19	68.65	61	Good	1	0	1	10	0				
		Direct Toppling	6.63	8	48.75	66.25	67.25	Good	0	0	2	6	0				
		Oblique Toppling	10.23	10	66.25	70	66.25	Good	0	0	0	10	0				
8A	62	034/85	Planar	0	0												
		Wedge	17.65	5	35	75.65	none	Good	0	1	0	4	0				
		Direct Toppling	5.88	4	73.25	77	73.25	Good	0	0	0	4	0				
		Oblique Toppling	13.07	0													
9A	57	022/85	Planar	10	3	29.5	69.6	none	Good	0	1	0	2	0			
		Wedge	12.12	3	63	68.4	63	Good	0	0	0	3	0				
		Direct Toppling	4.44	0													
		Oblique Toppling	22.22	3	68.25	68.25	69.25	Good	0	0	0	3	0				

Table 6 The summary of SMR, failure mode, critical joints, and intersections

Station	No.	Face slope	Failures	Intersection point	joint sets	RMR	SMR	SMR class	SMR stability
1	1A	003/85	Wedge	031/85	086/87,323/88	55	60	Normal	Partially stable
			Wedge	010/80	086/87,045/80	55	27.5	Bad	Unstable
			Direct Toppling	none	171/59	55	52.5	Normal	Partially stable
	1B	355/88	Wedge	341/88	360/88,323/88	55	52.5	Normal	Partially stable
	1C	087/88	Wedge	081/78	360/88,045/80	55	27.5	Bad	Unstable
2	1D	317/89	Wedge	341/88	360/88,323/88	55	50	Normal	Partially stable
	1E	233/78	Wedge	238/69	224/70,323/88	55	27.5	Bad	Unstable
	2A	325/80	Wedge	045/55	316/89,120/80	53	59	Normal	Partially stable
			Wedge	232/80	251/88,316/89	53	48	Normal	Partially stable
	2B	255/83	Wedge	227/39	316/89,140/86	53	47.6	Normal	Partially stable
			Wedge	231/79	316/89,212/80	53	48	Normal	Partially stable
			Wedge	230/75	181/80,316/89	53	49	Normal	Partially stable
	2C	225/84	Wedge	232/80	251/88,316/89	53	25.5	Bad	Unstable
			Wedge	210/78	251/81,140/86	53	33	Bad	Unstable
			Wedge	223/80	251/81,212/80	53	18	Very Bad	Completely unstable
			Wedge	212/78	251/81,181/80	53	33	Bad	Unstable
			Wedge	227/39	316/89,140/86	53	8	Very Bad	Completely unstable
			Wedge	231/79	316/89,212/80	53	25.5	Bad	Unstable
			Wedge	210/79	181/80,140/86	53	33	Bad	Unstable
	2D	353/85	Wedge	230/75	181/80,316/89	53	25.5	Bad	Unstable
			Wedge	045/55	120/80,316/89	53	59	Normal	Partially stable
3	3A	020/89	Wedge	062/72	120/80,140/86	53	59	Normal	Partially stable
			Planar	none	278/75	54	60	Normal	Partially stable
			Planar	none	312/48	54	60	Normal	Partially stable
			Wedge	311/72	011/81,278/75	54	60	Normal	Partially stable
			Wedge	072/72	011/81,081/72	54	60	Normal	Partially stable
			Wedge	290/46	011/81,312/48	54	60	Normal	Partially stable
			Wedge	033/80	011/81,092/85	54	34	Bad	Unstable
			Wedge	012/29	312/48,050/35	54	52.2	Normal	Partially stable
			Wedge	004/34	312/48,081/72	54	39.6	Bad	Unstable
			Wedge	005/34	312/48,092/85	54	39.6	Bad	Unstable
	3B	095/89	Wedge	004/26	050/35,092/85	54	52.2	Normal	Partially stable
			Wedge	001/25	050/35,278/75	54	52.2	Normal	Partially stable
			Wedge	000/26	081/72,278/75	54	52.2	Normal	Partially stable
			Planar	none	312/48	54	60	Normal	Partially stable
			Planar	none	278/75	54	60	Normal	Partially stable
			Wedge	097/26	011/81,050/35	54	45	Normal	Partially stable
			Wedge	072/72	011/81,081/72	54	60	Normal	Partially stable
			Wedge	311/72	011/81,278/75	54	60	Normal	Partially stable
			Direct Toppling	none	312/48	54	60	Normal	Partially stable
			Direct Toppling	none	317/20	54	60	Normal	Partially stable
	3C	328/87	Direct Toppling	none	011/81	54	60	Normal	Partially stable
			Direct Toppling	none	278/75	54	9	Very Bad	Completely unstable
			Direct Toppling	none	092/85	54	60	Normal	Partially stable
			Flexural Toppling	none	050/35	54	60	Normal	Partially stable
			Flexural Toppling	none	011/81	54	60	Normal	Partially stable
			Flexural Toppling	none	081/72	54	60	Normal	Partially stable
	3D	122/87	Wedge	290/46	011/81,312/48	54	60	Normal	Partially stable
			Wedge	311/72	011/81,278/75	54	27	Bad	Unstable
4	4A	260/78	Wedge	072/72	081/72,011/81	54	60	Normal	Partially stable
			Wedge	072/72	081/72,011/81	54	60	Normal	Partially stable
			Wedge	097/26	050/35,011/81	54	59.4	Normal	Partially stable
			Direct Toppling	none	312/48	54	47.75	Normal	Partially stable
			Direct Toppling	none	278/75	54	59	Normal	Partially stable
			Wedge	262/74	310/79,327/83	59	24	Bad	Unstable
			Wedge	270/60	360/90,251/61	59	23	Bad	Unstable
			Wedge	250/61	251/61,327/83	59	23	Bad	Unstable
			Wedge	276/77	242/79,310/79	59	39	Bad	Unstable
			Wedge	240/61	251/61,310/79	59	32	Bad	Unstable
5	5A	062/65	Wedge	271/78	242/79,327/83	59	56.5	Normal	Partially stable
			Oblique Toppling	none	Almost	59	70.25 to 74	Good	Stable
			Wedge	none	Almost	59	66.5 to 73.1	Good	Stable
			Direct Toppling	none	Almost	59	64 to 70.25	Good	Stable
	6A	004/81	Direct Toppling	none	193/76	59	52.75	Normal	Partially stable
			Direct Toppling	none	196/80	59	56.5	Normal	Partially stable
			Flexural Toppling	none	Almost	59	70.25 to 74	Good	Stable
			Planar	none	Almost	59	71.6 to 74	Good	Stable
	6B	163/72	Direct Toppling	none	Almost	59	70.25	Good	Stable
			Direct Toppling	none	335/86	59	52.75	Normal	Partially stable
			Direct Toppling	none	327/88	59	56.5	Normal	Partially stable
			Direct Toppling	none	356/86	59	56.5	Normal	Partially stable
6	6C	337/81	Flexural Toppling	none	Almost	59	70.25	Good	Stable
			Wedge	none	Almost	59	65.5 to 73.1	Good	Stable
			Direct Toppling	none	Almost	59	70.25	Good	Stable
			Wedge	277/50	244/55,295/80	55	46	Normal	Partially stable
	7A	245/78	Wedge	277/50	244/55,342/71	55	28	Bad	Unstable
			Wedge	324/32	026/53,040/69	55	28	Bad	Unstable
	7B	264/78	Wedge	316/24	244/55,026/53	55	49.6	Normal	Partially stable
			Wedge	301/38	244/55,011/67	55	49.6	Normal	Partially stable
	7C	324/77	Wedge	218/52	244/55,295/80	55	19	Very Bad	Unstable
			Wedge	206/48	244/55,133/75	55	46	Normal	Partially stable
7	7D	227/77	Wedge	212/35	295/80,133/75	55	34.3	Bad	Unstable
			Wedge	277/50	244/55,342/71	55	28	Bad	Unstable
	7E	290/82	Wedge	301/38	244/55,011/67	55	34.3	Bad	Unstable
			Wedge	083/36	011/67,026/53	55	49.6	Normal	Partially stable
	7F	110/82	Wedge	113/38	060/52,040/69	55	19	Very Bad	Unstable
			Direct Toppling	none	295/80	55	48.75	Normal	Partially stable
	8A	034/85	Direct Toppling	none	277/50	55	52.5	Normal	Partially stable
			Wedge	053/51	345/73,128/78	62	35	Bad	Unstable
8	8A	034/85	Wedge	none	Almost	62	68 to 75.65	Good	Stable
			Direct Toppling	none	Almost	62	73.25 to 77	Good	Stable
	9A	022/85	Planar	none	014/81	57	29.5	Bad	Unstable
			Wedge	none	Almost	57	63 to 68.4	Good	Stable
9	9A	022/85	Direct Toppling	none	Almost	57	68.25	Good	Stable

Table 7 Support measures for stabilization based on Singh and Goel (2011)

Station	No.	Face slope	Failures	Intersection point	joint sets	RMR	SMR	SMR class	SMR stability	Suggested Supports
1	1A	003/85	Wedge	031/85	086/87,323/88	55	60	Normal	Partially stable	IIIa
			Wedge	010/80	086/87,045/80	55	27.5	Bad	Unstable	IVb
			Direct Toppling	none	171/59	55	52.5	Normal	Partially stable	IIIa
	1B	355/88	Wedge	341/88	360/88,323/88	55	52.5	Normal	Partially stable	IIIa
	1C	087/88	Wedge	081/78	360/88,045/80	55	27.5	Bad	Unstable	IVb
2	1D	317/89	Wedge	341/88	360/88,323/88	55	50	Normal	Partially stable	IIIb
			Wedge	233/78	224/70,323/88	55	27.5	Bad	Unstable	IVb
			Wedge	045/55	316/89,120/80	53	59	Normal	Partially stable	IIIa
			Wedge	232/80	251/88,316/89	53	48	Normal	Partially stable	IIIb
			Wedge	227/39	316/89,140/86	53	47.6	Normal	Partially stable	IIIb
	2B	255/83	Wedge	231/79	316/89,212/80	53	48	Normal	Partially stable	IIIb
			Wedge	230/75	181/80,316/89	53	49	Normal	Partially stable	IIIb
			Wedge	232/80	251/88,316/89	53	25.5	Bad	Unstable	IVb
			Wedge	210/78	251/81,140/86	53	33	Bad	Unstable	IVa
			Wedge	223/80	251/81,212/80	53	18	Very Bad	Completely unstable	Va
	2C	225/84	Wedge	212/78	251/81,181/80	53	33	Bad	Unstable	IVa
			Wedge	227/39	316/89,140/86	53	8	Very Bad	Completely unstable	Error/failure
			Wedge	231/79	316/89,212/80	53	25.5	Bad	Unstable	IVb
			Wedge	210/79	181/80,140/86	53	33	Bad	Unstable	IVa
			Wedge	230/75	181/80,316/89	53	25.5	Bad	Unstable	IVb
	2D	353/85	Wedge	045/55	120/80,316/89	53	59	Normal	Partially stable	IIIa
			Wedge	062/72	120/80,140/86	53	59	Normal	Partially stable	IIIa
			Planar	none	278/75	54	60	Normal	Partially stable	IIIa
			Planar	none	312/48	54	60	Normal	Partially stable	IIIa
			Wedge	311/72	011/81,278/75	54	60	Normal	Partially stable	IIIa
3	3A	020/89	Wedge	072/72	011/81,081/72	54	60	Normal	Partially stable	IIIa
			Wedge	290/46	011/81,312/48	54	60	Normal	Partially stable	IIIa
			Wedge	033/80	011/81,092/85	54	34	Bad	Unstable	IVa
			Wedge	012/29	312/48,050/35	54	52.2	Normal	Partially stable	IIIa
			Wedge	004/34	312/48,081/72	54	39.6	Bad	Unstable	IVa
			Wedge	005/34	312/48,092/85	54	39.6	Bad	Unstable	IVa
			Wedge	004/26	050/35,092/85	54	52.2	Normal	Partially stable	IIIa
			Wedge	001/25	050/35,278/75	54	52.2	Normal	Partially stable	IIIa
			Wedge	000/26	081/72,278/75	54	52.2	Normal	Partially stable	IIIa
			Planar	none	312/48	54	60	Normal	Partially stable	IIIa
	3B	095/89	Planar	none	278/75	54	60	Normal	Partially stable	IIIa
			Wedge	097/26	011/81,050/35	54	45	Normal	Partially stable	IIIb
			Wedge	072/72	011/81,081/72	54	60	Normal	Partially stable	IIIa
			Wedge	311/72	011/81,278/75	54	60	Normal	Partially stable	IIIa
			Direct Toppling	none	312/48	54	60	Normal	Partially stable	IIIa
			Direct Toppling	none	317/20	54	60	Normal	Partially stable	IIIa
			Direct Toppling	none	011/81	54	60	Normal	Partially stable	IIIa
			Direct Toppling	none	278/75	54	9	Very Bad	Completely unstable	Error/failure
			Direct Toppling	none	092/85	54	60	Normal	Partially stable	IIIa
			Flexural Toppling	none	050/35	54	60	Normal	Partially stable	IIIa
			Flexural Toppling	none	011/81	54	60	Normal	Partially stable	IIIa
			Flexural Toppling	none	081/72	54	60	Normal	Partially stable	IIIa
	3C	328/87	Wedge	290/46	011/81,312/48	54	60	Normal	Partially stable	IIIa
			Wedge	311/72	011/81,278/75	54	27	Bad	Unstable	IVb
			Wedge	072/72	081/72,011/81	54	60	Normal	Partially stable	IIIa
	3D	122/87	Wedge	072/72	081/72,011/81	54	60	Normal	Partially stable	IIIa
			Wedge	097/26	050/35,011/81	54	59.4	Normal	Partially stable	IIIa
			Direct Toppling	none	312/48	54	47.75	Normal	Partially stable	IIIb
			Direct Toppling	none	278/75	54	59	Normal	Partially stable	IIIa
4	4A	260/78	Wedge	262/74	310/79,327/83	59	24	Bad	Unstable	IVb
			Wedge	270/60	360/90,251/61	59	23	Bad	Unstable	IVb
			Wedge	250/61	251/61,327/83	59	23	Bad	Unstable	IVb
			Wedge	276/77	242/79,310/79	59	39	Bad	Unstable	IVa
			Wedge	240/61	251/61,310/79	59	32	Bad	Unstable	IVa
5	5A	062/65	Oblique Toppling	none	Almost	59	70.25 to 74	Good	Stable	IIa
6	6A	004/81	Wedge	none	Almost	59	66.5 to 73.1	Good	Stable	IIB to IIa
			Direct Toppling	none	Almost	59	64 to 70.25	Good	Stable	IIB
			Direct Toppling	none	193/76	59	52.75	Normal	Partially stable	IIIa
			Direct Toppling	none	196/80	59	56.5	Normal	Partially stable	IIIa
			Flexural Toppling	none	Almost	59	70.25 to 74	Good	Stable	IIa
	6B	163/72	Planar	none	Almost	59	71.6 to 74	Good	Stable	IIa
			Direct Toppling	none	Almost	59	70.25	Good	Stable	IIB
			Direct Toppling	none	335/86	59	52.75	Normal	Partially stable	IIIa
			Direct Toppling	none	327/88	59	56.5	Normal	Partially stable	IIIa
			Direct Toppling	none	356/86	59	56.5	Normal	Partially stable	IIIa
			Flexural Toppling	none	Almost	59	70.25	Good	Stable	IIB
	6C	337/81	Wedge	none	Almost	59	65.5 to 73.1	Good	Stable	IIB to IIa
			Direct Toppling	none	Almost	59	70.25	Good	Stable	Ib
7	7A	245/78	Wedge	218/52	244/55,295/80	55	46	Normal	Partially stable	IIIb
			Wedge	277/50	244/55,342/71	55	28	Bad	Unstable	IVb
	7B	264/78	Wedge	324/32	026/53,040/69	55	28	Bad	Unstable	IVb
			Wedge	316/24	244/55,026/53	55	49.6	Normal	Partially stable	IIIb
	7C	324/77	Wedge	301/38	244/55,011/67	55	49.6	Normal	Partially stable	IIIb
			Wedge	218/52	244/55,295/80	55	19	Very Bad	Unstable	Va
			Wedge	206/48	244/55,133/75	55	46	Normal	Partially stable	IIIb
	7D	227/77	Wedge	212/35	295/80,133/75	55	34.3	Bad	Unstable	IVa
			Wedge	277/50	244/55,342/71	55	28	Bad	Unstable	IVb
	7E	290/82	Wedge	301/38	244/55,011/67	55	34.3	Bad	Unstable	IVa
			Wedge	083/36	011/67,026/53	55	49.6	Normal	Partially stable	IIIb
8	8A	034/85	Wedge	113/38	060/52,040/69	55	19	Very Bad	Unstable	Va
			Direct Toppling	none	295/80	55	48.75	Normal	Partially stable	IIIb
			Direct Toppling	none	277/50	55	52.5	Normal	Partially stable	IIIa
			Wedge	053/51	345/73,128/78	62	35	Bad	Unstable	IVa
			Direct Toppling	none	Almost	62	73.25 to 77	Good	Stable	IIa
9	9A	022/85	Planar	none	014/81	57	29.5	Bad	Unstable	IVb
			Wedge	none	Almost	57	63 to 68.4	Good	Stable	IIB
			Direct Toppling	none	Almost	57	68.25	Good	Stable	IIB

References

- Bieniawski, Z.T., 1989, Engineering rock mass classification: a complete manual for engineers and geologists in mining, civil, and petroleum engineering (p.250), Wiley and Sons.
- Deere, D.U. & Miller, R.P. (1966). Engineering classification and index properties for intact rock. Technical report No. AFNL-TR-65-116 Air Force Weapons Laboratory, New Mexico.
- DMR, (2005). Sinkhole potential map of Thailand. Environmental Geology Division, Department of Mineral Resources, Bangkok.
- DMR, (2016). Seismic hazard map of Thailand. Environmental Geology Division, Department of Mineral Resources, Bangkok.
- Khundee, K., Kererattanasathian, V., Hongsaban, N., Khlonkratoke, A., Maihom P., and Tewa, C., (2019). Coastal changes along the Petra Beach to Ao Noon Bay, La-ngu District, Satun Province. Environmental Geology Division, Department of Mineral Resources, Bangkok. 15 p.
- Meesook, A. (2014). Lithostratigraphy, Faunal assemblages, Biodiversity, Paleocology and Environment of Deposition of the Cambrian-Permian Rocks in Satun Province, Peninsular Thailand, Technical report contract No. 39/2557, Bureau of Geological survey, Department of Mineral Resources.
- Romana, M., 1985, New adjustment ratings for application of Bieniawski classification to slopes, in: Proceedings of the International Symposium on the Role of Rock Mechanics in Excavations for Mining and Civil Works. International Society of Rock Mechanics, Zacatecas, p.49-53
- Sinsakul, S., 1988, Geological map of Amphoe Langu (4922 I) map sheet, scale 1:50,000, Department of Mineral Resources, Bangkok, Thailand.
- Singh, B., Geol, R. K.2011, Engineering Rock Mass Classification, Tunneling, foundation, and landslides; Elsevier: New York
- Sinsakul, S., Tiypairach, S., Chaimanee, N., and Aramprayoon, B., 2002, Coastal change along the Andaman Sea coast of Thailand, Geological survey division, Department of Mineral Resources, Bangkok, 58p.
- Thepju, W., Yamansabedean, N., & Bamrungsong, P., 2017. Karst features in Satun Geopark, Satun province. in DMR-CCOP-TNCU Technical Seminar on “ Biostratigraphy and Karst Morphology of Satun Aspiring Geopark, 13-14 July 2017, The Berkeley, Hotel, Pratunam, Bangkok, Thailand, p.50-59.
- Tiypairach, S., 2004. Geological map of Ban Pak Bara (4922 IV) map sheet, scale 1:50,000, Department of Mineral Resources, Bangkok, Thailand.
- Waltham, A.C., and Fookes, P.G. (2003). Engineering classification of karst ground conditions. Quarterly Journal of Engineering Geology and Hydrogeology.
- Waltham, T., Bell, F. and Culshaw, M. (2005). Sinkholes and Subsidence, Karst and Cavernous Rocks in Engineering and Construction. Praxis Publishing, UK.
- Wongvanish, T. (1990). Lithostratigraphy, sedimentology, and diagenesis of the Ordovician carbonates, Southern Thailand. University of Tasmania, unpublished Ph.D. thesis, 215 p.